

November 2023

## Release Notice

---

All rights reserved, including intellectual property rights. Technical data subject to modifications and delivery subject to availability. Any liability that the data and illustrations are complete, actual or correct is excluded. Designations may be trademarks and/or copyrights of the respective manufacturer, the use of which by third parties for their own purposes may infringe the rights of such owner.

© 2017-2023 Fujitsu Technology Solutions GmbH. All rights reserved.

The Fujitsu brand and the Fujitsu logo are registered trademarks of Fujitsu Limited, Japan in Europe and other countries.

BS2000 is a trademark of Fujitsu Technology Solutions GmbH in Europe.

<b>1 General</b>	<b>3</b>
1.1 Ordering	3
1.2 Delivery	3
1.3 Documentation	3
<b>2 Support matrix</b>	<b>4</b>
2.1 FC switches - Fabric OS (FOS) V7.x	4
2.2 FC switches - Fabric OS (FOS) V8.x	5
2.3 FC switches - Fabric OS (FOS) V9.x	6
<b>3 Technical information</b>	<b>7</b>
3.1 Software configuration	7
3.2 BS2000 specific settings	7
3.3 Discontinued functions (and those to be discontinued)	7
3.4 Restrictions	7
3.5 Procedure in the event of errors	7
<b>4 Hardware requirements</b>	<b>8</b>
4.1 SE Server	8

# 1 General

This release notice supplements the release notes for the FC switches and FOS versions and contains a list of the FC switches and FOS versions supported by BS2000 as well as dependencies and operating instructions for connecting FC switches to BS2000 servers.

\*14 The release level is of: November 2023.

\*14 Changes to release level September 2023 are marked with \*14  
\*13 Changes to release level March 2023 are marked with \*13  
\*12 Changes to release level August 2022 are marked with \*12  
\*11 Changes to release level January 2022 are marked with \*11  
\*10 Changes to release level October 2021 are marked with \*10  
\*09 Changes to release level July 2021 are marked with \*09  
\*08 Changes to release level May 2021 are marked with \*08  
\*07 Changes to release level April 2021 are marked with \*07  
\*06 Changes to release level August 2020 are marked with \*06  
\*05 Changes to release level February 2020 are marked with \*05  
\*04 Changes to release level July 2019 are marked with \*04  
\*03 Changes to release level February 2018 are marked with \*03  
\*02 Changes to release level October 2017 are marked with \*02  
\*01 Changes to release level August 2017 are marked with \*01

\*13 This and further ongoing release notices are available online by  
<http://bs2manuals.ts.fujitsu.com>.

Additionally, the following release notices must be taken into account (depending on the installed software):

\*06 BS2000 OSD/XC  
\*06 BS2000 OS DX

## 1.1 Ordering

The purchase of the FC switches can be ordered in general via your local distributor.

## 1.2 Delivery

-

## 1.3 Documentation

\*11 The documentation is also available on the internet at <https://bs2manuals.ts.fujitsu.com>.  
\*11 There you will find both individual manuals and (under the „SoftBooks“ tab) the ISO  
\*11 image of a DVD with the entire inventory.

\*05 Please ask your service provider for the current FC switch documentation.

See the support sites of your service provider for the announced “End-of-Life” dates.

## 2 Support matrix

### 2.1 FC switches - Fabric OS (FOS) V7.x

	FOS v7.x.x (release date for BS2000)	Brocade FC Switch					Remarks
		8G	16G				
		300	6505	6510	6520	DCX 8510	
*02	7.4.2c (23.02.2018)	X					
*05	7.4.2f (14.08.2020)	X					
*06	7.4.2g (07.04.2021)	X					
*09	7.4.2h (12.10.2021)	X					
*14	7.4.2j1 (14.07.2022)	x					

X: supported

## 2.2 FC switches - Fabric OS (FOS) V8.x

	FOS v8.x.x (release date for BS2000)	Brocade FC Switch								Remarks
		16G				32G				
		6505	6510	6520	DCX 8510	G610	G620	G630	X6-4	
*05	8.2.2b (14.08.2020)	X	X	X	X	X	X	X	X	
*07	8.2.2d (12.05.2021)	X	X	X	X	X	X	X	X	
*09	8.2.2d4 (12.10.2021)	X	X	X	X	X	X	X	X	
*10	8.2.3a2 (10.01.2022)	X	X	X	X					
*12	8.2.3c1 (24.02.2023)	X	X	X	X					
*13	8.2.3d (08.09.2023)	X	X	X	X					

X: supported

## 2.3 FC switches - Fabric OS (FOS) V9.x

	FOS v9.x.x (release date for BS2000)	Brocade FC Switch								Remarks	
		32G					64G				
		G610	G620	G630	X6-4	X6-8	G720	G730	X7-4		X7-8
*08	9.0.1a (05.07.2021)						X		X	X	
*09	9.0.1b (12.10.2021)	X	X	X	X	X	X		X	X	
*10	9.0.1c (10.01.2022)	X	X	X	X	X	X		X	X	
*11	9.1.0b (29.07.2022)	X	X	X	X	X	X	X	X	X	
*12	9.1.1b (06.03.2023)	X	X	X	X	X	X	X	X	X	
*14	9.2.0a (07.11.2023)						X	X	X	X	

X: supported

## **3 Technical information**

### **3.1 Software configuration**

Support is granted for SE Server with BS2000 as of V20.0.

### **3.2 BS2000 specific settings**

-

### **3.3 Discontinued functions (and those to be discontinued)**

-

### **3.4 Restrictions**

In BS2000 environment no tests with any fabric/switch monitoring software have been conducted.

### **3.5 Procedure in the event of errors**

In case of hardware or firmware errors, please contact your local Service provider.  
If a general error occurs in BS2000, please pay attention to the regarding instructions in the BS2000 release notices.

## 4 Hardware requirements

\*13 BS2000 Server: SE730, SE710, SE700B, SE500B, SE330, SE320, SE310, SE300B

### 4.1 SE Server

\*13 SU730:  
\*13 - 16Gb FC channel

\*04 SU710:  
\*04 - 16Gb FC channel

SU700B, SU500B:  
- 8Gb FC channel

\*13 SU330:  
\*13 - LPe35002  
\*13 - LPe31002

\*06 SU320:  
\*06 - LPe35002

\*04 SU310:  
\*04 - LPe31002  
\*04 - LPe32002

SU300B:  
- LPe12002  
- LPe16002  
- LPe31002